

8.2. Cleaning of PC surfaces

Cleaning and spot removal:

Special cleaning material is not necessary. To avoid surface damage no aggressive cleaning material should be used.

Standard cleaning:

Use a lukewarm mixture of soap and water or a mild household detergent. Dirt can be removed with a cloth or sponge. All surfaces to be washed with cold water and to be dried with a soft cloth to avoid water marks.

Persistent marks can be cleaned with the following solvents: Methanol or Ethanol, Turpentine, Heptan or Hexan, Butanol or Isopropyl.

Do not use alkaline cleaners!

Do not handle the surface with razor blades or any other sharp-edged instruments.

8.3. Cleaning of PMMA surfaces

Cleaning and spot removal:

We recommend a special "Plastic Intensive Cleaner" from Burnus GmbH / Darmstadt. This cleaning material preserves the facing and does not leave any marks behind.

For standard cleaning

we recommend a cleaning material of the same company as above called "Kunststoff Reiniger+Pfleger". This cleaning material is without toxic vapours and does not leave any marks on the plastic surface behind.

Also usable are window cleaning materials. Please do not use any aggressive detergents. Do try some different brands like Ajax®.